## U.S. From and Darin Singapoins Hos Protestand and Promoting Your Hot St

EDA Home<sup>3</sup> Medical Devices<sup>4</sup> Databases<sup>5</sup> Class 2 Device Recall Stryker Orthopaedics Specialty Triathlon Tibial Alignment Handle with Secondary Lock 6 510(k) |DeNovo8| Registration &

Adverse |Recalls<sup>11</sup>|PMA<sup>12</sup>|HDE<sup>13</sup>|Classification<sup>14</sup>|Standards<sup>15</sup>

Listing<sup>9</sup>


Events<sup>10</sup>

CFR Title 21<sup>16</sup>|Radiation-Emitting Products<sup>17</sup>|X-Ray Assembler<sup>18</sup>|Medsun Reports<sup>19</sup>|CLIA<sup>20</sup>|TPLC<sup>21</sup>

New Search

Back to Search Results

Class 2 Device Recall Stryker Orthopaedics Specialty Triathlon **Tibial Alignment Handle with** Secondary Lock



Recall Date

August 11, 2016

Recall Status<sup>1</sup>

Open

**Recall Number** 

Z-2390-2016

Recall Event ID

74619<sup>23</sup>

510(K)Number

K123486<sup>24</sup>

**Product Classification** 

Prosthesis, knee, patello/femorotibial, semi-constrained, uncemented, porous, coated,

polymer/metal/25 - Product Code MBH26

Product

Stryker Orthopaedics Specialty Triathlon Tibial Alignment Handle with Secondary

Lock, Non-Sterile,

Used to complement or replace the standard instruments used during the

implantation of hip, knee, trauma and upper extremities implants

**Code Information** 

Catalog No: I-K3254TA00

Lot Nos: F6E13243, F6L13864, F6M14078, F6S14667, F6S14831, F6W15444, F6W15406,

F7C15943, F7H16099 and F7L16994

Recalling Firm/ Manufacturer

Stryker Howmedica Osteonics Corp.

325 Corporate Dr

Mahwah NJ 07430-2006

For Additional **Information Contact**  Mr. Michael Van Ryn

201-831-5000

Manufacturer Reason

for Recall

It was reported that the secondary locking mechanism, and its corresponding components, disassociated from the Specialty Triathlon Tibial Alignment Handle with Secondary Lock Assembly during surgery. Upon further investigation, it was discovered that the weld, which was intended to hold the secondary locking mechanism together, did not meet the weld size

specified on the engineering drawing.

**FDA Determined** Cause 2

Process control

Action

Stryker sent an Urgent Product Recall letter dated June 24, 2016, with a Business Reply Form attached to all affected customers. The letter identified the product, the problem, and the action to be taken by the customer. Customers were asked to inform users of the Urgent Product Recall letter and forward the notice to all those individuals who need to be aware within their organization. Customers were instructed to return all affected product at their location to: Stryker C/O Stericycle 2670 Executive Dr., Suite A Indianapolis, IN 46241 Customers were also instructed to complete and sign the enclosed Business Reply Form and fax it to 888-912-7352 or email to Stericycle at strykerortho4582@stericycle.com. Customers with questions were advised to call (201) 831-6693. For questions regarding this recall call 201-831-5000.

**Quantity in Commerce** 

47 units

Distribution

Nationwide Distribution to FL, IN, LA, NC, PA, TN and UT