

### Important Medical Device Information

#### Updates on Instructions for Use (IFU) regarding Erosion for the AMPLATZER™ Septal Occluder (ASO)

<b>Affected products</b>	AMPLATZER™ Septal Occluder (ASO) Model # ASD-004 to 040
<b>Adverse Event</b> <b>Specifically erosion</b>	Erosion, though rare, is a potentially serious life threatening event with symptomatic signals including chest pain, shortness of breath, fainting, and difficulty breathing. If erosion occurs, emergency surgery may be required for a successful outcome.
<b>Risk of erosion</b>	The risk for potential erosion has remained stable over time. The world-wide estimated incidence rate for erosion is between 0.1% and 0.3%.
<b>Revision of ASO Instructions for Use</b>	<p>The primary revisions to the IFU are pertaining to additional information for physicians regarding the risks and symptoms of erosion. The IFU has been updated and clarified as follows:</p> <ul style="list-style-type: none"> <li>• The contraindication for defect margins less than 5 mm has been updated to include the inferior vena cava rim</li> <li>• Warnings have been updated or modified to include: <ul style="list-style-type: none"> <li>○ patients with a retro-aortic rim of less than 5 mm in any echocardiographic plane or patients in whom the device impinges on the aortic root may be at increased risk of erosion</li> <li>○ placement of the ASD occluder may impact future cardiac interventions, for example transseptal puncture and mitral valve repair</li> <li>○ do not release the device from the delivery cable if the device does not conform to its original configuration or if the device position is unstable or if the device interferes with any adjacent cardiac structure, such as superior vena cava (SVC) pulmonic valve (PV), mitral valve (MV), coronary sinus (CS) or aorta (AO). Recapture the device and redeploy. If still unsatisfactory, recapture the device and replace with a new device (<i>italicized and underlined text shows modified warning</i>)</li> </ul> </li> <li>• The adverse events were updated to include more detail on the rare event of erosion, including the rate of tissue erosion of 1-3 per 1000 patients</li> <li>• The following additional changes were also made to the IFU to align the US and international IFUs and add to the effective use of the device: <ul style="list-style-type: none"> <li>○ Clinical follow-up recommendations have been updated. Specifically, follow-up with a cardiologist and echocardiograms are recommended at implant, 1 day post-implant, pre-discharge, and again at 1 week, 1 month, 6 months, and 12 months post-implant. Clinical follow-up with a cardiologist annually thereafter is also recommended</li> <li>○ Patient awareness has been emphasized. Specifically, patients should be educated to seek immediate medical attention that includes an echocardiogram, if they develop signs or symptoms of hemodynamic instability such as chest pain, arrhythmia, fainting, or shortness of breath.</li> <li>○ Patients should be instructed to avoid strenuous activity for a minimum 1 month postdevice implant or as directed by their physician. Strenuous activities may lead to the increased risk of adverse events including erosion. Patients should be reminded that if they experience any symptoms of shortness of breath or chest pain at any time and especially after strenuous activity,</li> </ul> </li> </ul>

