

24th January 2020

URGENT – FIELD SAFETY NOTICE

Type of Action			Recall
Teleflex Reference			EIF-000392
Commercial Name			Pilling CLEAR ADVANTAGE® Disposable Aortic Punch
Product Code			Lot Number
353440	DP-52K	MDP-44K	Refer to Appendix 2
DP-28K	DP-56K	MDP-48K	
DP-36K	DP-60K	MDP-52K	
DP-40K	MDP-28K	MDP-56K	
DP-44K	MDP-36K	MDP-60K	
DP-48K	MDP-40K		

Dear Customer,

Teleflex has initiated a voluntary Field Safety Corrective Action for the above listed product codes.

Description of the problem & immediate actions required

Teleflex is recalling the above product codes and lots listed in Appendix 2. There is a potential for the device packaging to become compromised; thus, the sterility of the device cannot be guaranteed. If device sterility is compromised and the product is used it could lead to contamination and infection which could compromise anastomosis and contribute to wound infection. No complaints, patient injuries or deaths have been reported at this time.

Our records indicate that you have received products that are subject to this recall.

Depending on your device location please adhere to the following Action list:

Device location	Action List Number
Medical facilities	1
Distributors	2

Action list number 1 – Medical facilities

1. We request that you check your inventory for product within the scope of this FSCA. Users should cease use and distribution of impacted product and quarantine immediately.
2. If you do have stock in scope of this FSCA, mark the according checkbox on the Acknowledgement Form (Appendix 1) and contact customer service by calling the phone number mentioned below. Customer service will issue you with a return number. Write the return number into the respective field in the Acknowledgement Form and return this form immediately to Customer Service.
3. If you do not have stock in scope of this FSCA mark the according checkbox on the Acknowledgement Form (Appendix 1) and return the form to the fax number or e-Mail address mentioned below.

4. Teleflex (or your local dealer) will issue a credit note upon receipt of the returned affected product.

Action list number 2 – Distributors

1. Provide this field safety notice to all customers who have received product in scope of this FSCA. Your customer is then required to complete the acknowledgement form and return to you.
2. We request that you check your inventory for product within the scope of this FSCA. Cease use and distribution of impacted product and quarantine immediately. You may then return all product in scope to Teleflex.
3. As a distributor, you are then required to confirm to Teleflex that you have completed the field activity outlined above. Upon completion of your actions, please forward the completed Acknowledgement Form to Customer Service.
4. Please be aware that all European Economic Area/Switzerland (EEA/CH) and Turkey Member State Competent Authorities in which Teleflex distribute directly will be notified by Teleflex.
5. If you have further distributed product outside of your country, please notify Teleflex by return email to the e-Mail address below.
6. If you are a distributor and/or have a reporting responsibility within or outside the EEA/CH/TR region, please notify your local Competent Authority of this action. Please forward the notification and all communication with your local competent authority to Teleflex.

Teleflex

Teleflex informs all customers, employees of Teleflex and distributors of this Field Safety Corrective Action.

Transmission of this Field Safety Notice

This notice should be passed on to all persons who need to be aware within your organisation or to any organisation where the potentially affected devices have been transferred. Please consider end users, clinicians, risk managers, supply chain/distribution centres etc. in the circulation of this notice. Maintain awareness of this notice until all required actions have been completed in your organisation.

Contact reference person

Should you require any further information or support concerning this issue, please contact:

Customer Service:

Contact: Nicole Morawiec

FAX: +41 (0) 31 818 40 93

Telephone: +41 (0) 31 818 40 90

Email: info.ch@teleflex.com

Please be advised that all Economic Area/Switzerland (EEA/CH) and Turkey Member State Competent Authorities to which Teleflex distribute directly will be notified by Teleflex. Teleflex is committed to providing high quality, safe and effective products. We sincerely apologise for any inconvenience this action may cause your operations. If you have any other questions, feel free to contact your local sales representative or Customer Service.

For and on behalf of Teleflex,

Padraig Hegarty

Padraig Hegarty VP, QA (Manufacturing)

Appendix 1

Customer No

FIELD SAFETY CORRECTIVE ACTION
ACKNOWLEDGEMENT FORM

PRODUCT FIELD ACTION BY TELEFLEX – IMMEDIATE ATTENTION REQUIRED

Ref. EIF-000392

RETURN COMPLETED FORM IMMEDIATELY TO:

FAX: +41 (0) 31 818 40 93

Email: info.ch@teleflex.com

<input type="checkbox"/> We confirm receipt of this FSN and have completed the required actions contained therein. We confirm that our inventory does NOT include products affected by this Field Action.	<input type="checkbox"/> We confirm receipt of this FSN and have completed the required actions contained therein. We confirm our inventory DOES include products affected by this Field Action. The use and further distribution of the affected products is stopped. All products are put on hold and the amount below will be returned. Return Authorisation No: _____
--	--

PLEASE PRINT PRODUCT QUANTITY NUMBERS CLEARLY

PRODUCT NUMBER	LOT NUMBER	QUANTITY (Returning)
<ul style="list-style-type: none"> Include a copy of the completed Acknowledgement Form in the returns package with the returned units Ensure the RAN number is clearly visible on the returns package Please label returns as "Field Safety Returns" 		

Complete this Acknowledgement form and return immediately by using fax number or e-Mail address above.

INSTITUTION NAME (EG NAME OF HOSPITAL, HEALTH CARE ORGANISATION)	
INSITIUTION ADDRESS	Phone/FAX
FORM COMPLETED BY:	Stamp
PRINT NAME: _____ SIGNATURE: _____	
DATE	

Appendix 2 - Product Codes and Lots in scope of EIF-000392

Code	Lots					
353440	74B1500674					
DP-28K	74A1501140	74B1602364	74E1700597	74G1602599	74H1900357	74L1501549
	74A1601253	74B1900832	74E1800886	74G1700636	74J1501218	74L1501977
	74A1601254	74C1501113	74E1802643	74G1700637	74J1501754	74L1501978
	74A1602903	74C1600966	74E1901667	74G1700718	74J1501755	74L1600387
	74A1602904	74C1600972	74F1502019	74G1900066	74J1601180	74L1600389
	74A1603168	74C1600976	74F1600350	74G1900340	74J1603181	74L1602761
	74A1603170	74C1600977	74F1602476	74G1902629	74J1800844	74L1700357
	74A1701154	74C1702793	74F1602477	74G1903756	74K1500475	74L1800444
	74A1802567	74C1702794	74F1702731	74H1502508	74K1500476	74L1803409
	74A1903113	74C1800357	74F1800411	74H1502510	74K1501684	74L1901787
	74A1903146	74D1600123	74F1802291	74H1601384	74K1501685	74M1601318
	74B1501366	74D1601266	74F1802292	74H1602748	74K1900124	74M1602080
	74B1501710	74D1601524	74G1500954	74H1700589	74K1900125	74M1800915
	74B1600576	74D1602673	74G1500955	74H1700590	74K1900133	74M1800916
	74B1600580	74D1802317	74G1503008	74H1701427	74K1901814	74M1801620
	74B1601613	74E1600837	74G1503009	74H1701863	74L1501239	74M1900014
74B1601616	74E1700596	74G1602598	74H1800764	74L1501548		
DP-36K	74A1601251	74C1501114	74E1600361	74F1901768	74H1602749	74K1901790
	74A1602049	74C1501504	74E1600362	74G1501254	74H1802543	74L1501933
	74A1602205	74C1600454	74E1700383	74G1501584	74H1802910	74L1501934
	74A1603169	74C1600978	74E1700598	74G1502240	74H1900354	74L1502651
	74A1801612	74C1702795	74E1800887	74G1502247	74H1901509	74L1502668
	74A1901239	74C1702796	74E1802644	74G1601150	74J1501761	74L1602762
	74A1902997	74C1800358	74E1900552	74G1601151	74J1501762	74L1702282
	74A1903148	74D1503157	74E1901665	74G1700719	74J1702333	74L1702978
	74B1501361	74D1600124	74F1500725	74G1702124	74J1702528	74L1800993
	74B1600581	74D1600125	74F1502017	74G1702125	74J1703089	74L1803139
	74B1601617	74D1802318	74F1502713	74G1802091	74J1900939	74L1803408
	74B1602365	74D1900834	74F1502714	74G1902121	74J1901700	74M1601319
	74B1602372	74D1901907	74F1600351	74H1500734	74K1500480	74M1702625
	74B1800721	74E1500848	74F1703304	74H1500735	74K1501130	74M1801251
	74B1800722	74E1501779	74F1801505	74H1502517	74K1501131	74M1801622
	74B1902990	74E1502618	74F1802293	74H1600757	74K1502964	74M1900012
74B1903028	74E1503095	74F1900940	74H1601385	74K1600559		
DP-40K	74A1501146	74A1602181	74A1702660	74A1901901	74B1602046	74C1503228
	74A1501148	74A1602360	74A1800595	74B1501126	74B1800506	74C1503232
	74A1502433	74A1602361	74A1800596	74B1501358	74B1800723	74C1600455
	74A1502434	74A1603161	74A1801613	74B1502260	74B1801756	74C1600460
	74A1502851	74A1603162	74A1802148	74B1502261	74B1802580	74C1600967
	74A1502852	74A1603163	74A1802150	74B1503151	74C1501122	74C1600979
	74A1503453	74A1700378	74A1802568	74B1503152	74C1501123	74C1600980
	74A1601248	74A1700766	74A1900243	74B1600577	74C1501505	74C1702893
	74A1601249	74A1700767	74A1900244	74B1600582	74C1502259	74C1702894
74A1601250	74A1702659	74A1901240	74B1601618	74C1502260	74C1800359	

Appendix 2 - Product Codes and Lots in scope of EIF-000392

Code	Lots					
DP-40K (Cont.)	74C1800360	74E1503093	74F1601983	74G1900067	74H1903474	74K1602893
	74C1801150	74E1503099	74F1602478	74G1902118	74J1500711	74K1602894
	74C1900330	74E1600838	74F1602479	74G1902119	74J1500712	74K1700910
	74C1900332	74E1600839	74F1603239	74G1902833	74J1501214	74K1701639
	74C1900811	74E1601257	74F1603240	74G1903729	74J1501215	74K1702121
	74C1900812	74E1602244	74F1700828	74H1500732	74J1501766	74K1702122
	74C1901597	74E1602245	74F1701130	74H1501603	74J1501767	74K1702866
	74C1902227	74E1602810	74F1701131	74H1502506	74J1502404	74K1802890
	74C1902228	74E1602811	74F1702095	74H1502507	74J1502405	74K1900758
	74D1500077	74E1700599	74F1702096	74H1502530	74J1600424	74K1900759
	74D1500078	74E1700600	74F1702733	74H1600758	74J1600425	74K1901792
	74D1501647	74E1701203	74F1702734	74H1600759	74J1601181	74K1902250
	74D1501648	74E1701234	74F1703305	74H1601386	74J1601737	74L1500801
	74D1503172	74E1701236	74F1800418	74H1602468	74J1602579	74L1500810
	74D1600213	74E1701755	74F1801506	74H1602469	74J1602677	74L1501230
	74D1600214	74E1701758	74F1802294	74H1602750	74J1602678	74L1501231
	74D1600927	74E1703220	74F1802710	74H1602751	74J1700737	74L1501983
	74D1601538	74E1703236	74F1802711	74H1700591	74J1700738	74L1502663
	74D1602013	74E1801602	74F1900935	74H1700592	74J1701829	74L1600400
	74D1602014	74E1801603	74F1900936	74H1701429	74J1702529	74L1600440
	74D1602676	74E1802105	74F1900937	74H1701431	74J1702530	74L1601327
	74D1700564	74E1802106	74F1901099	74H1701839	74J1703090	74L1601328
	74D1700954	74E1802645	74F1901117	74H1701869	74J1703091	74L1602113
	74D1700955	74E1802984	74F1901761	74H1702709	74J1800845	74L1602763
	74D1701179	74E1900554	74G1500951	74H1702710	74J1801321	74L1602764
	74D1702440	74E1900593	74G1501744	74H1703164	74J1801322	74L1700358
	74D1801512	74E1901447	74G1502237	74H1703165	74J1802104	74L1700359
	74D1802103	74E1901448	74G1503006	74H1800761	74J1802105	74L1701122
	74D1802104	74E1901663	74G1600720	74H1800763	74J1802736	74L1701124
	74D1802319	74E1901664	74G1601769	74H1800838	74J1900237	74L1701786
	74D1802693	74E1902715	74G1602120	74H1801707	74J1900956	74L1702283
	74D1802694	74E1903772	74G1602121	74H1802544	74J1901697	74L1702979
	74D1900484	74F1500753	74G1602600	74H1802911	74J1901698	74L1800558
	74D1900485	74F1500754	74G1700638	74H1802912	74J1903043	74L1800559
	74D1900657	74F1501151	74G1700639	74H1900352	74K1500471	74L1800994
	74D1900659	74F1501152	74G1701299	74H1900353	74K1500472	74L1800995
	74D1901505	74F1502021	74G1701314	74H1901108	74K1501121	74L1801431
	74D1902167	74F1502022	74G1702119	74H1901109	74K1501122	74L1803140
	74D1902810	74F1502217	74G1702120	74H1901115	74K1501680	74L1900199
	74D1902811	74F1502710	74G1800767	74H1901116	74K1502261	74L1900200
74D1902812	74F1502711	74G1800768	74H1901510	74K1502262	74L1900201	
74E1501782	74F1600352	74G1801515	74H1902119	74K1502270	74L1900202	
74E1501783	74F1601101	74G1802092	74H1902737	74K1600560	74L1900361	
74E1502616	74F1601102	74G1802093	74H1902738	74K1601326	74L1900362	
74E1502617	74F1601325	74G1802678	74H1903398	74K1602034	74L1900858	

Appendix 2 - Product Codes and Lots in scope of EIF-000392

Code	Lots					
DP-40K (Cont.)	74L1900859	74M1500805	74M1601314	74M1701819	74M1801624	74M1900367
	74L1901403	74M1600393	74M1602082	74M1701820	74M1900010	74M1901094
	74L1901404	74M1600394	74M1701016	74M1801252	74M1900017	74M1901095
	74L1901885	74M1601313	74M1701017	74M1801253	74M1900366	
DP-44K	74A1501153	74D1600217	74E1900553	74H1502520	74J1700739	74L1700360
	74A1502848	74D1601525	74E1903148	74H1502909	74J1701830	74L1701125
	74A1602180	74D1602016	74E1903763	74H1600761	74J1701831	74L1701787
	74A1800598	74D1602268	74F1600354	74H1600762	74J1702532	74L1701788
	74A1801615	74D1602679	74F1600355	74H1601224	74J1703093	74L1702285
	74A1801616	74D1700951	74F1601104	74H1601387	74J1800846	74L1702981
	74A1802152	74D1701786	74F1601140	74H1602470	74J1801323	74L1702982
	74A1802569	74D1702441	74F1601984	74H1602471	74J1802106	74L1800560
	74A1900362	74D1802105	74F1601985	74H1700594	74J1900625	74L1800561
	74A1901242	74D1802106	74F1603241	74H1700595	74J1901696	74L1800997
	74A1901899	74D1900483	74F1603242	74H1701435	74J1903042	74L1800998
	74A1902221	74D1900658	74F1702097	74H1701864	74K1500483	74L1801771
	74A1902222	74D1901506	74F1702735	74H1701865	74K1501132	74L1803136
	74A1902354	74D1902168	74F1800868	74H1702712	74K1501688	74L1803261
	74B1501363	74E1500841	74F1801508	74H1702713	74K1600561	74L1901191
	74B1502275	74E1500842	74F1802712	74H1703166	74K1601328	74L1901200
	74B1601620	74E1501992	74F1900938	74H1703282	74K1601329	74L1901201
	74B1602048	74E1503098	74G1502238	74H1800765	74K1700912	74L1901407
	74B1602049	74E1600364	74G1503014	74H1800840	74K1700913	74M1600396
	74B1800508	74E1601723	74G1600917	74H1800841	74K1701641	74M1601316
	74B1800725	74E1601724	74G1601771	74H1801709	74K1701642	74M1601317
	74B1800726	74E1602248	74G1601772	74H1801710	74K1702868	74M1602089
	74B1801757	74E1602812	74G1602122	74H1802546	74K1702869	74M1602090
	74B1802581	74E1700602	74G1602123	74H1802914	74K1900131	74M1702628
	74B1802582	74E1701406	74G1602673	74H1900355	74K1901789	74M1702629
	74C1501117	74E1702791	74G1602718	74H1901113	74K1901813	74M1900011
	74C1501506	74E1702792	74G1700640	74H1901511	74L1501242	74M1900372
	74C1600973	74E1702796	74G1701317	74H1902120	74L1502469	74M1900689
	74C1600975	74E1702797	74G1701318	74H1903403	74L1600402	74M1901097
	74C1702792	74E1800889	74G1801516	74J1600426	74L1600403	
	74C1902226	74E1801605	74G1802681	74J1600427	74L1601647	
	74D1500076	74E1801606	74G1900338	74J1601203	74L1601648	
74D1501516	74E1802108	74G1902123	74J1602434	74L1602115		
74D1501645	74E1802109	74G1902633	74J1603182	74L1602766		
74D1600216	74E1802987	74G1903757	74J1603183	74L1602767		
DP-48K	74A1502850	74A1801617	74B1502262	74B1802583	74C1801152	74D1600931
	74A1602182	74A1802153	74B1503158	74B1901661	74C1900329	74D1601537
	74A1602901	74A1901238	74B1601609	74C1501119	74C1900618	74D1602017
	74A1603164	74A1901900	74B1800505	74C1600462	74D1600226	74D1602018
	74A1700763	74A1902355	74B1800719	74C1600974	74D1600227	74D1700939
	74A1800600	74B1501128	74B1800727	74C1600982	74D1600930	74D1700943

Appendix 2 - Product Codes and Lots in scope of EIF-000392

Code	Lots					
DP-48K (Cont.)	74D1702442	74F1600357	74G1601774	74H1701867	74J1703095	74K1900760
	74D1702443	74F1600358	74G1602124	74H1701868	74J1800847	74K1901336
	74D1802107	74F1601105	74G1602719	74H1702714	74J1801324	74L1500803
	74D1802321	74F1601137	74G1602720	74H1800767	74J1802108	74L1600443
	74D1901508	74F1601986	74G1701319	74H1800843	74J1901706	74L1602116
	74D1902169	74F1602009	74G1701320	74H1800844	74J1903044	74L1701123
	74E1600842	74F1603243	74G1800770	74H1802548	74K1501123	74L1701789
	74E1602249	74F1702099	74G1801517	74H1802549	74K1501124	74L1702286
	74E1602813	74F1702736	74G1900337	74H1802915	74K1600562	74L1800443
	74E1701837	74F1702737	74G1900339	74H1900356	74K1600563	74L1800999
	74E1701838	74F1703306	74G1902120	74H1901512	74K1602037	74L1803265
	74E1801607	74F1800866	74G1903728	74J1501216	74K1602038	74M1600397
	74E1801608	74F1801510	74G1903758	74J1501759	74K1700915	74M1602092
	74E1802646	74F1802296	74H1601389	74J1600428	74K1701643	74M1701020
	74E1802647	74F1900939	74H1601390	74J1601183	74K1701644	74M1702630
	74E1902716	74F1901122	74H1602472	74J1601783	74K1702870	74M1702631
	74E1902717	74F1902895	74H1602752	74J1602085	74K1702871	74M1800913
	74F1502712	74G1501749	74H1602753	74J1700740	74K1900128	74M1900368
	74F1503522	74G1601773	74H1700596	74J1701832	74K1900129	74M1901096
	DP-52K	74A1601258	74D1700800	74F1602482	74H1600764	74K1602778
74A1700762		74D1700820	74F1701133	74H1701443	74K1700916	
74A1800602		74D1701167	74F1701134	74H1702715	74K1702872	
74A1903114		74D1802322	74F1800869	74H1800846	74K1900132	
74B1501364		74D1802323	74F1800870	74H1801712	74K1900761	
74B1503155		74E1600843	74F1801512	74H1801713	74K1901795	
74B1600584		74E1602250	74F1901098	74H1802550	74K1902045	
74B1602050		74E1602814	74G1500952	74J1601733	74K1902545	
74B1800510		74E1700899	74G1700720	74J1602581	74L1501241	
74B1800729		74E1701840	74G1900341	74J1701833	74L1602118	
74B1802584		74E1701841	74G1902122	74J1802110	74L1700361	
74B1900830		74E1800897	74G1902834	74J1900239	74L1800555	
74C1501507		74E1900596	74G1903730	74J1901704	74L1803267	
74C1902229		74F1500755	74G1903755	74K1501689	74M1600398	
74D1602269	74F1601106	74H1600763	74K1600564	74M1601320		
DP-56K	74A1501142	74B1600585	74D1501515	74F1500724	74H1702716	74K1902252
	74A1601256	74B1601614	74D1502568	74F1502020	74J1702533	74L1501976
	74A1602204	74B1601622	74E1500845	74F1702103	74K1500481	74L1502672
	74A1603172	74B1602367	74E1502580	74F1800871	74K1501683	74M1900365
	74A1800603	74B1800720	74E1602815	74F1801514	74K1502970	74M1900840
	74B1500704	74C1501508	74E1701843	74F1801515	74K1602779	74M1901098
	74B1502274	74C1600968	74E1701844	74F1802297	74K1900126	74M1901275
	74B1600578	74D1500075	74E1800898	74G1902124	74K1900127	
DP-60K	74A1500172	74E1502579	74M1602094	74E1800901	74G1902125	
	74D1501639	74A1602907	74H1700597	74E1800902	74K1901815	
	74E1500846	74E1602816	74H1702717	74G1900342		

Appendix 2 - Product Codes and Lots in scope of EIF-000392

Code	Lots					
MDP-28K	74A1502835	74A1902357	74E1701845	74F1902101	74H1801714	
	74A1601252	74B1501360	74E1901451	74F1902891	74H1802551	74K1901816
	74A1602906	74B1601615	74F1500722	74F1902892	74J1702534	74L1702287
	74A1800642	74B1602374	74F1501155	74H1500733	74J1901705	
	74A1802572	74B1801755	74F1800872	74H1702718	74K1800082	
	74A1901243	74D1700801	74F1802298	74H1702719	74K1900135	
MDP-36K	74A1602184	74B1602375	74F1500984	74H1601392	74J1802111	74L1702288
	74A1602185	74C1702803	74F1703309	74H1701444	74K1500473	74L1702289
	74A1802573	74C1702804	74F1800873	74H1702720	74K1602780	74L1901405
	74A1901218	74C1802507	74F1901968	74H1801715	74K1701646	74L1901411
	74A1902223	74C1802508	74F1902108	74H1802552	74K1900134	74M1901099
	74B1501261	74E1600363	74G1500956	74H1802553	74L1500804	
	74B1600586	74E1701846	74G1502248	74H1902743	74L1500805	
	74B1601623	74E1701847	74H1502513	74J1500701	74L1501981	
74B1602368	74E1902721	74H1502514	74J1702535	74L1501982		
MDP-40K	74A1503439	74C1802506	74F1502715	74G1602722	74J1502407	74K1801695
	74A1601257	74C1900617	74F1503526	74G1800771	74J1601185	74L1500807
	74A1602908	74D1600957	74F1503527	74G1801518	74J1601186	74L1500808
	74A1603166	74D1600958	74F1600359	74G1802094	74J1700494	74L1501935
	74A1700734	74D1601536	74F1601332	74G1902832	74J1700742	74L1501936
	74A1701848	74D1602680	74F1601333	74H1500736	74J1802112	74L1602768
	74A1802574	74D1700567	74F1603244	74H1502518	74J1901699	74L1602769
	74B1501131	74D1700568	74F1702104	74H1502519	74K1500478	74L1701126
	74B1501365	74D1800226	74F1702105	74H1602475	74K1500479	74L1702983
	74B1503154	74D1800227	74F1702738	74H1602476	74K1502266	74L1900759
	74B1600587	74E1502619	74F1702739	74H1701446	74K1502268	74L1900860
	74B1601624	74E1503096	74F1703310	74H1702721	74K1600565	74M1602095
	74B1602369	74E1601726	74F1902081	74H1902739	74K1601332	74M1701824
	74B1802585	74E1602817	74F1902177	74H1902740	74K1602781	74M1701825
	74C1600456	74E1602818	74F1902178	74H1902741	74K1602782	74M1900369
	74C1600984	74F1500759	74G1501993	74H1903402	74K1701647	74M1901093
	74C1600985	74F1501153	74G1501994	74J1501756	74K1702867	
	74C1802505	74F1502018	74G1602721	74J1502406	74K1800961	
MDP-44K	74A1502836	74B1902383	74D1801513	74F1802299	74H1702722	74K1702124
	74A1601255	74C1503233	74D1801514	74F1901118	74H1801716	74K1800962
	74A1602179	74C1702806	74D1900660	74G1500953	74H1900358	74K1801699
	74A1700760	74C1801154	74E1500844	74G1601152	74H1901513	74L1501916
	74A1700761	74C1900328	74E1601486	74G1602723	74H1902742	74L1502660
	74A1800643	74C1901596	74E1602252	74G1700721	74J1603175	74L1601649
	74A1800644	74D1601526	74E1602819	74G1802095	74J1603176	74L1700363
	74A1801620	74D1601535	74E1701849	74H1502515	74J1700743	74L1700364
	74A1802575	74D1602681	74E1900594	74H1601394	74J1703098	74L1702290
	74B1501359	74D1700916	74F1600360	74H1601395	74J1800849	74L1702984
	74B1600575	74D1800228	74F1601138	74H1701448	74J1901702	74L1801776
	74B1600588	74D1800229	74F1703312	74H1701449	74K1602783	74L1900363

Appendix 2 - Product Codes and Lots in scope of EIF-000392

Code	Lots					
MDP-44K (Cont.)	74L1900760	74M1602086	74M1701826			
	74L1901239	74M1701022	74M1900013			
MDP-48K	74A1602178	74C1902230	74F1600361	74H1502516	74J1800850	74K1801700
	74A1801621	74D1503161	74F1600362	74H1601396	74J1800851	74K1801701
	74A1802576	74D1602682	74F1601982	74H1602477	74J1802113	74L1501243
	74A1802577	74D1700565	74F1602484	74H1603433	74J1802740	74L1602770
	74A1900255	74D1700566	74F1700830	74H1701450	74J1900241	74L1700365
	74A1902358	74D1800230	74F1800874	74H1701840	74J1901703	74L1701127
	74B1600589	74D1800231	74F1802300	74H1802554	74K1600566	74L1803269
	74B1800512	74E1501776	74G1600722	74H1901514	74K1600567	74L1901406
	74B1800730	74E1601487	74G1602125	74H1903400	74K1601333	74M1601321
	74B1802586	74E1601494	74G1802096	74J1501758	74K1601334	74M1602097
	74C1501509	74E1703226	74G1802684	74J1600431	74K1602784	74M1701023
	74C1801155	74E1801610	74G1902626	74J1601187	74K1700917	74M1701827
	74C1802503	74E1802702	74G1902835	74J1601188	74K1702873	74M1701828
	74C1802504	74E1901452	74G1903731	74J1702563	74K1800963	
MDP-52K	74A1603171	74C1502258	74D1902815	74F1902890	74H1701451	74L1702291
	74A1603177	74C1600457	74F1500987	74F1902893	74H1701452	74M1600399
	74A1801622	74C1600464	74F1600363	74G1501260	74H1801717	74M1900015
	74A1900570	74D1602270	74F1702740	74G1503013	74J1502610	74M1900690
	74A1903115	74D1700574	74F1702741	74G1801519	74K1502265	74M1901101
	74B1501133	74D1700575	74F1800875	74H1502512	74K1602785	
	74C1501510	74D1800232	74F1902113	74H1601397	74L1500806	
MDP-56K	74A1502837	74A1601260	74A1602183	74B1600579	74C1600458	74D1901016
MDP-60K	74A1500226	74B1503153	74C1900613	74F1602485	74H1500728	74J1602582
	74A1601259	74B1602370	74D1500074	74F1702742	74H1502910	74J1901701
	74A1700732	74C1502256	74D1700569	74F1800876	74H1601398	74K1800083
	74A1801623	74C1600459	74D1801515	74G1501745	74H1702723	74K1901793
	74A1802579	74C1600970	74E1700603	74G1801520	74H1702724	74L1601650
	74A1901241	74C1800374	74F1500723	74G1902631	74H1801718	74L1700366
	74B1501262	74C1802502	74F1502701	74G1902818	74H1802917	