

20 March 2014

**URGENT - FIELD SAFETY NOTICE**

<b>TYPE OF ACTION:</b>	Recall	
<b>TELEFLEX REFERENCE:</b>	40004241A	
<b>COMMERCIAL NAME</b>	<b>PART</b>	<b>LOT</b>
Bondek Plus	EP4049N	02A1003137
DEKLENE® II Polypropylene Suture	E7-4578	02D0901672
	ED-6072	02C1002218
		02E1002342
		02J0902517
	ED-6276	02F0902457
	ED-6896	02C0900661
		02C1002207
		02D0900634
		02D1100186
		02E0901921
		02E0902608
		02E1301581
		02J0900501
		02K0901590
		02K0902406
02L0900676		
02M0901869		
ED-853	02G1002594	
ED-863	02D0902457	
	02M0901348	
POLYLENE Polyester Suture	E13-6351	02F0902446
	E13-6354	02F0902439
	E13-6399	02F0902436
silky' II POLYDEK® Polyester Suture	E6-545	02F0902443

Dear Customer,

**1. Details of affected devices**

Teleflex has initiated a voluntary Field Safety Corrective Action for the above listed products.

**2. Description of the problem**

Teleflex is recalling the products referenced above because they did not meet minimum needle attachment strength requirements. If affected product is used and failure occurs, delay in procedure, injury infection and bleeding may occur requiring medical and/or surgical intervention.

