REPUBLIC OF LEBANON MINISTRY OF PUBLIC HEALTH

The Director General



جمهورية اللبنان وزارة الصحة العامة المدير العام

رقم المحفوظات: ٥٥٥ ٨ ٣٠ رقم اللصادر ٢٥٢٥ ١ ١٧١٨ بيروت، في: ٢٦ تريادل ٢٠١٣

جانب نقيب المستشفيات الخاصة في لبنان

الموضوع: إشعار بمتابعة جهاز طبي ADM/MDM Ball Impactor Tips and ADM Rim Impactor Tips

الجهاز المعنى بالمتابعة:


- ADM/MDM Ball Impactor Tips and ADM Rim Impactor Tips
- Trade Mark: Stryker
- Local Representative: Ets.F.A Kettaneh

بناء على التقرير الصادر عن الوكالة الأوسترالية TGA والذي يشير الى وجود خلل في عمل الصنف الوارد أعلاه، نرجو منكم تعميم هذه النشرة على جميع المستشفيات المعنية.

مرفق ربطاً:

التقرير الصادر عن الوكالة الأوسترالية TGA

. دانرة البرامج والمشاريع المستشفيات الحكومية المحفوظات



Recall detail

Type of Product ⁱ	Medical Device
TGA Recall Reference	RC-2013-RN-01033-1
Product Name/Description ⁱⁱⁱ	ADM/MDM Ball Impactor Tip and ADM Rim Impactor Tip (reusable surgical instrument used to implant Stryker's Automatic Dual Mobility (ADM) and/or the Modular Dual Mobility (MDM) Acetabular Systems)
	ADM/MDM Ball Impactor Tip Catalogue Numbers: 12350013 (12350303A-T, 12350306-T, 12350306V-T, 12350306C-T)
	ADM Rim Impactor Tip Catalogue Numbers: 12350014 (12350303A-T)
	All Lot Numbers Affected
	ARTG Number: 181721
Recall Action Level ^{iv}	Hospital
Recall Action Classification ^v	Class II
Recall Action Commencement Date	4/10/2013
Responsible Entity ^{vii}	Stryker Australia Pty Ltd
Reason / Issue ^{viji}	Stryker has received complaints associated with cracks and/or fractures of the Ball Impactor Tip and Rim Impactor Tip instruments. The potential hazards include; - Cracked or fractured Ball impactor Tip/Rim Impactor Tip - Loose fragments form the Ball impactor Tip/Rim Impactor Tip - Insufficient locking strength of the MDM liner (Ball Impactor Tip only).
Recall Action ^{ix}	Recall for Product Correction
Recall Action Instructions ^x	Stryker is releasing updated surgical procedures and also updating the loan dockets, recommending the use of a slotted mallet to be used to impact the impactor handle, and emphasising that all tips should be inspected for deformation and cracks before use.
Contact Information ^{xi}	02 9467 1111 - Stryker Orthopaedics

Footnotes

ⁱ Type of Product: Medicine, Medical Device, or Biological

ii TGA Recall Reference: Unique number given by the TGA

iii Product Name/Description: Brand name (including active ingredient for medicines) and may include generic reference for the kind of medical devices. Includes all necessary information such as affected: catalogue / model and / or batch / serial numbers.